


**Part Number: MA02-0174-C06-8**

*Description:* SMA Crimp Bulkhead Jack, Nickel Plated  
*To suit cable types:* AMC-174, LBC100, LBC100 LSZH, LMR100, RG174, RG188, RG316, WBC100

*Strip Dimensions*  
 A=7mm, B=2.5mm, C=2.5mm

*Cable Preparation*



■ Assembly Instructions

1) Slide the ferrule onto the cable and strip the cable to the dimensions as shown, taking care not to nick the centre conductor or braid.



2) Solder the contact onto the centre core and slide the contact into the body, ensuring that the cable braid is on the outside of the connector mandril and that the contact is located in accordance with MIL-C-39012 interface dimensional requirements.



3) Slide the ferrule forward and crimp.



*Recommended Crimp Tool(s):* GCT-D316 PCC0308  
*Crimp Hex. Sizes:* 3.25mm Hex., Solder centre core