

Part Number: NT10-0519-C06


Description: N Type Crimp Jack

To suit cable types: LBC400, LBC400 ExtraFlex

Strip Dimensions

A=9mm, B=2mm, C=4mm

Cable Preparation




■ Assembly Instructions

1) Slide the ferrule onto the cable and strip the cable to the dimensions as shown, taking care not to nick the centre conductor or braid.



2) Solder the contact onto the centre core and slide the contact into the body until it captivates, ensuring that the cable braid is on the outside of the connector mandril.



3) Slide the ferrule forward and crimp.



Recommended Crimp Tool(s): GCT-0213 GCT-0519

Crimp Hex. Sizes: 10.90mm Hex., Solder centre core